

Field Assembly Connector

Field Assembly Connector is a very convenient optical fiber connector which can be field assembled and installed quickly, it is the best choice for drop cable termination.

It has been widely used in the world with features such as rapid installation, time saving, compatible with standard SC and FC connectors/adaptors, and it can raise the efficiency of FTTH service provisioning.

Features

- Can be assembled on fiber or cable sheath
- · Easy assembly, no special tools required
- · The connection can be verified easily after assembly



Application

- Fiber Outlets
- Fiber Termination Box
- Fiber DP/NAP Box

Specifications

Item	Specifications	
Connector type	UPC or APC	
Insertion loss (dB)	Maximum ≤0.50; typical ≤0.3	
Return loss (dB)	UPC≥50; APC≥55	
Tensile load (N)	≥20	
Working temperature (°C)	-40 ~ +7 0	


Classification

Product type	Adaptor type	UPC/APC
Machanical Field Assembly Connector	SC	UPC
Mechanical Field Assembly Connector		APC




Field Assembly Connector

Structure (Mechanical Field Assembly Connector)



Features

- Can be assembled on fiber or cable sheath
- No special tools required;
- Re-assembly is available;
- Pre-installed fiber, pre-polished ferrule surface
- Applicable cable: 2.0x3.0mm drop cable



Assembly Procedure

